

Operator's manual



TruTool TPC 165 (1A1)

Table of contents

1	Safety	4
1.1	General safety information	4
1.2	Specific safety information for Panel Cutter TPC 165	5
2	Description	7
2.1	Intended use	7
2.2	Technical data	9
2.3	Icons	9
2.4	Noise and vibration information	10
3	Setting work	12
3.1	Changing/tensioning the tool	13
4	Operation	15
4.1	Working with the Panel Cutter	15
	Checking the tool	16
	Working procedure	16
	Overload protective device on the motor	18
4.2	Main machine position	18
4.3	Table markings	19
4.4	Plunging depth	20
4.5	Guide rails	20
	Working with the guide rail	20
4.6	Cutting along scribed line	21
4.7	Slide rails and wearing plate	22
	Replacing the slide rails	23
	Replacing the wearing plate	23
	Replacing the front wearing plate	23
4.8	Exhaust system	23
4.9	Electronic signal display	24
5	Maintenance and repairs	26
5.1	Maintenance	26
	Set screw - Adjusting the ratchet	27
5.2	Repairs	28
	Replacing carbon brushes	28

6	Accessories and consumables	29
6.1	Ordering consumables	29
7	Appendix: Declaration of conformity, guarantee, replacement parts lists	30

1. Safety

1.1 General safety information

WARNING



- Read all safety warnings and all instructions including those in the brochure also supplied.
- Failure to follow the warnings and instructions may result in electric shock, fire and/or serious injury.
- Save all warnings and instructions for future reference.

DANGER

Electrical voltage! Risk of fatal injury due to electric shock!

- Remove the plug from the plug socket before undertaking any maintenance work on the machine.
- Check the plug, cable and machine for damage each time before using the machine.
- Keep the machine dry and do not operate it in damp rooms.
- Connect the fault current (FI) circuit breaker with a maximum breaking current of 30 mA when using the electric tool outside.
- Only use original TRUMPF accessories.
- If the connection cable has to be replaced, this may only be done by the manufacturer or an authorized dealer to avoid safety hazards.

WARNING

Damage to the machine due to improper handling.

- Wear safety glasses, hearing protection, breathing protection, protective gloves and working shoes when working.
- Connect the plug only when the machine is switched off. Pull the power plug after use.
- Do not carry the machine by the cable.
- Have maintenance carried out by specialists.

Note

If the power cable is to be replaced, it should be procured from the manufacturer or an authorized dealer to avoid safety hazards.

1.2 Specific safety information for Panel Cutter TPC 165

DANGER

Electrical voltage! Risk of fatal injury due to electric shock!

- Hold the machine with both hands on the insulated handle during machining.
- Always keep the power cable behind the device and do not pull it over sharp edges.
- Do not perform any work that may cause the machine to come into contact with hidden power lines or its own cable. Contact with a live conductor can cause metallic machine parts to become live and can lead to an electric shock.

WARNING

Risk of injury to hands.

- Do not reach into the processing line with your hands.
- Do not reach into the saw chain with your hands.
- Do not reach under the workpiece. The saw chain and the blade are unguarded when they are in the swivelled out status.
- Never hold the workpiece in your hands or over your leg during machining.

WARNING

Health risks especially damage to muscles and joints due to strong vibrations during operation.

- Carry out machining at normal feed power.


 **WARNING****Risk of injury due to improper handling!**

- Make sure the machine is always in a stable position when operating it in order to absorb any possible kickback forces.
- Always operate the machine away from your body.
- Do not carry out overhead work on the machine.
- The machine may only be operated with a protective cover.
- If the saw falls down, check that the saw chain and saw blade move freely afterwards. The protective cover and other parts must not be touched.
- Before putting the machine down, ensure that the blade is folded in.
- If the saw should get stuck in the material, release the switch and do not move the saw in the material until the saw chain stops. When restarting, center the saw blade in the kerf and make sure that the teeth of the saw chain are no longer stuck.
- Blades of the predecessor models (e. g. TP 150-0 and TPC 150-2) as well as damaged blades must not be used.
- Follow the instructions for lubrication, chain tensioning and changing accessories. An improperly tensioned or lubricated chain can break.
- Keep the handles clean and free of oil and grease. Greasy, oily handles are slippery and will lead to loss of control.

 **WARNING****Risk of injury through defective brake!**

- Check the brake before every use. The brake must stop movement of the chain within 2 s. If there is a defect, inform TRUMPF Service.
- Do not clamp the switch for the saw chain and swivel lever for the blade.
- If the saw falls down, check the brake for perfect operation afterwards.

2. Description



TruTool TPC 165

Fig. 67302

2.1 Intended use



Danger of injury and health hazard!





- Only use the machine for the work and materials described under "Intended use".
- Do not cut materials containing asbestos.

The TRUMPF Panel Cutter TPC 165 is an electrically operated hand-held device:

- For commercial use in industry and trade.
- For efficiently cutting panels with metal outer shells and polyurethane or polyisocyanurate rigid foam insulation (roof and wall panels).
- For easy piercing in panels for producing cornered cutouts.

-
- For cutting along a scribed line.
 - For cutting with a guide rail.

2.2 Technical data

	Other countries			USA
	Values			
Voltage	230 V	120 V	110 V	120 V
Frequency	50/60 Hz	50/60 Hz	50/60 Hz	50/60 Hz
Working speed	4 m/min	4 m/min	4 m/min	9.8 ft/min
Nominal power consumption	1400 W	1400 W	1400 W	1400 W
Idle stroke rate n_0	2300/min	2300/min	2300/min	2300/min
Cutting track width	4 mm	4 mm	4 mm	4 mm
Weight	9.6 kg	9.6 kg	9.6 kg	21.2 lbs
Safety class	II / 	II / 	II / 	II / 

Technical data

Tab. 1

	Other countries	USA
	Permissible material thicknesses	
Individual material thickness for steel up to 400 N/mm ₂	0.9 mm	0.9 mm (0.035 in)
With insulation made of polyurethane foam (PUR) and polyisocyanurate foam (PIR)	165 mm	165 mm (6.4 in)

Permissible material thicknesses

Tab. 2

	Other countries	USA
	Minimum cutouts	
Blade 165	340 x 340 mm	340 x 340 mm (13.5 x 13.5 in)



Minimum cutouts






Tab. 3

2.3 Icons

Note

The following symbols are important for reading and understanding the operator's manual. The correct interpretation of the symbols will help you operate the machine better and safer.

Icon	Name	Meaning
	Read operator's manual	Read the operator's manual and safety information in their entirety before starting up the machine. Closely follow the instructions given.
	Wear safety glasses.	Chips could fly out of the tool.

Icon	Name	Meaning
	Wear gloves.	Chips could fly out of the tool.
	Wear hearing protection.	Noise emission value can be exceeded.
	Danger of injury due to rotating saw.	Do not reach into the saw chain with your hands.
	Safety class II	Indicates a doubly insulated tool.
	Alternating current	Type or property of current
V	Volt	Voltage
A	Ampere	Current, current input
Hz	Hertz	Frequency (oscillations per second)
W	Watt	Power, power input
mm	Millimeters	Dimensions e.g.: material thickness, chamfer length
in	Inch	Dimensions e.g.: material thickness, chamfer length
n_o	Idle speed	Revolution speed without load
.../min	Revolutions/strokes per minute	Revolution speed, stroke rate per minute

Tab. 4

2.4 Noise and vibration information

WARNING

Noise emission value may be exceeded.

- Wear hearing protection.

WARNING

The vibration emission value can be exceeded!

- Select the right tools and exchange them in time in the event of wear.
- Have maintenance carried out by trained specialized technicians.
- Define additional safety measures for protecting the operator from the effect of vibrations (e. g. keep hands warm, organization of working procedures, machining at normal feed force).
- Depending on the operating conditions and state of the electric tool, the actual load might be higher or lower than the specified measured value.

WARNING

Health risks especially damage to muscles and joints due to strong vibrations during operation.

- Carry out machining at normal feed power.

Notes

- The specified vibration emission value was measured in accordance with a standardized testing procedure and can be used to compare one electric tool with another.
- The specified vibration emission value can also be applied for a provisional estimate of the vibration load.
- Times during which either the machine is switched off or running but not actually in use can considerably reduce the vibration load during the entire working period.

Designation of measured value	Unit	Value according to EN 60745
Vibration emission value a_h (vector sum of three directions)	m/s ²	5.1
Uncertainty K for vibration emission value	m/s ²	1.5
A-class acoustic pressure level L_{pA} typically	dB (A)	89
A-class acoustic power level L_{WA} typically	dB (A)	100
Uncertainty K for noise emission value	dB	3

Tab. 5

3. Setting work

⚠ DANGER

Risk of fatal injury due to electric shock!

- Remove the plug from the plug socket before changing the tool or undertaking any maintenance work on the machine.

NOTICE

Damage to property!

Wear and destruction of the saw chain and blade, tool failure.

- Do not tension the saw chain too tautly (see "Fig. 67306", pg. 14).
- When inserting the saw chain, always pay attention to the tooth direction.
- Do not operate the saw chain without lubricant (see "Tab. 8", pg. 26).
- Avoid collisions during work. Do not cut into nails, screws, etc.

NOTICE

Damage to property due to the wrong tools being used!

Reduction in service life of the tools.

- Depending on the application, use the right tools according to the following table.

	Panel thickness (outer plate + foam insulation)
Saw chain 165 with blade 165	max. 165 mm

Tab. 6

Both the saw chains as well as the blades are meant for processing panels with outer plates up to a tensile strength of 400 N/mm² and a thickness up to 0.9 mm. A panel thickness up to 165 mm with foam insulation can be processed.

The machine is suitable for cutting panels with the insulation materials polyurethane foam (PUR) and polyisocyanurate foam (PIR).

Note

If the structure of the panels to be processed vary from the above-described version (thicker outer plates or higher tensile strength, other insulation materials), it is to be expected that the service life of the saw chain and blade will be reduced. Also, penetrating into the material with the blade might be more difficult, or might not be possible at all.

3.1 Changing/tensioning the tool

Removing the saw chain




Fig. 67303

1. Loosen the hexagon-head screw (6) using a combination wrench (in the cover) and remove.
2. Take off the protective cover (5).
3. Shift the blade (3) by turning the chain tensioner (4) toward the chain wheel (1).
4. Lift the saw chain (2) with the blade (3) out of the chain wheel (1).

Checking the oil channel




Fig. 31844


NOTICE**Damage to property.**

A clogged oil channel can lead to increased wear or to the saw chain breaking.

- Clean the oil channel regularly.

Inserting the saw chain

5. Check the oil channel. It must not be dirty.
6. Insert a new saw chain in the blade and chain wheel. While doing so, pay attention to the running direction (arrow) of the saw chain.



Correct chain tension

Fig. 67306

Tensioning the saw chain

7. Shift the blade by turning the chain tensioner. Tension the saw chain until it can be lifted approx. 3 mm (dimension, see Fig. 67306) from the blade by hand (measuring point is middle of blade).
8. Stick on the protective cover.
9. Screw the protective firmly in place using the hexagon-head screws (6).
10. Loosen the hexagon-head screw (6) using a combination wrench (in the cover) with one turn.
11. Shift the blade by turning the chain tensioner.
12. Tension the saw chain until it can be lifted approx. 3 mm (dimension, see Fig. 67306) from the blade by hand (measuring point is middle of blade).
13. Screw the protective cover firmly in place.

4. Operation

4.1 Working with the Panel Cutter

⚠ CAUTION

Damage to property due to excessively high line voltage!

This could result in motor damage due to overload.

- Check the line voltage. The power supply voltage must correspond to the information on the nameplate of the machine.

⚠ WARNING

Risk of injury due to improper handling!

- Make sure the machine is always in a stable position when operating it.
- Never touch the tool while the machine is running.
- Always operate the machine away from your body.
- Do not carry out overhead work on the machine.
- The machine may only be operated with the protective cover.

2-hand control device

Work is performed with two-hand operation for all machine positions.



2-hand control device

Fig. 67304

When operating the machine ensure that the machine is held with both hands in such a way that both hands are kept away from the processing point.

Checking the tool

NOTICE**Damage to property caused by blunt tools!****Machine overload.**

- Check tools every hour for wear. Sharp saw blades have good cutting performance and prevent damage to the device. Change the saw chain in due time.
-

- Check whether both tools, the saw chain and the blade, are correctly mounted.

Working procedure

NOTICE**Damage to property!****Wear and destruction of the saw chain and blade, tool failure.**

- Do not tension the saw chain too tautly (see "Fig. 67306", pg. 14).
 - When inserting the saw chain, always pay attention to the tooth direction.
 - Do not operate the saw chain without lubricant (see "Tab. 8", pg. 26).
 - Avoid collisions during work. Do not cut into nails, screws, etc.
-

**Putting integrated
lubrication device into
operation when used for
first time**




Fig. 67305

**Working with the Panel
Cutter**

1. Fill the oil tank with punching and nibbling oil.
2. Press the release button (4)(see "Fig. 67305", pg. 17) and then press the switch (2).
Motor (1) switches on, saw chain (5) runs.
3. Keep the switch (2) pressed for approx. 2 minutes until both oil hoses have filled with oil.
4. Pierce into the material from above.

The machine is equipped with an electronic start-up current limiter. Therefore, make sure that the machine is only guided toward the workpiece when it is switched on and has reached its full speed.

When piercing into the full panel, the panel can kick back when the running tool comes into contact with it.

**Checking the chain tension
and oil level**

Notes

- A new chain will elongate and must be retensioned after approx. 15 - 20 cut meters.
 - If the saw chain jams during cutting, immediately switch off the motor (see "Fig. 67305", pg. 17) (2), retract the machine and restart.
5. Cut the material.

When cutting, the chain tension (section 3.2) and the oil level (oil level indicator below the angular gear) must be checked regularly.



Switching off the Panel Cutter

Tip

During cutting, the saw chain is constantly lubricated with the fully automatic lubricating device. The lubricating oil is usually sufficient for a cutting length of approx. 150 m.

6. Release the switch (2) (see "Fig. 67305", pg. 17).
The saw chain (5) will stop within 2 seconds and the motor shuts off.
7. Swing in the blade.
The blade is in its parking position and is thereby protected from contamination and damage.
8. Have the machine lie level with the table on the panel (6) or guide rail (3).

Overload protective device on the motor

Notes

- The appliance may switch off prematurely when affected by electromagnetic interference. The appliance will resume operation when the faults have been cleared.
 - If the motor temperature is too high, the motor limits the input power. The red indicator light (LED) on the motor lights up.
1. Allow the machine to run in idle until it has cooled down.
 2. Operate the machine normally after it has cooled down.

4.2 Main machine position

In the main machine position, the machine lies with the support table flat on the material and the blade is aligned vertically downward. Cutting in the main machine position generates a vertical cut.




Main machine position

Fig. 67307

4.3 Table markings

The three markings on the side of the table indicate the front and rear sides of the blades in the main machine position and the blade insertion positions. If the chain tension slackens, the actual cutting edge deviates from the marked position.



- | | | | | | |
|---|---|---|-------------------------|---|--------------------------|
| 1 | Blade insertion position in the support table | 3 | Front side of the blade | 5 | Marking for straight cut |
| 2 | Rear side of the blade | 4 | Cut marking, front | | |

Markings on the support table

Fig. 67308

For a straight cut, make sure that the marking (4) lies at the cut each time.

4.4 Plunging depth

The scale on the gear housing indicates the plunging depth of the blade in stages 0 - 12.




Fig. 67464

4.5 Guide rails


Using the guide rail (options)

Using the guide rail allows:

- a clean, straight cut.
- better machine guidance.
- easy processing of roof panels (trapezoidal shape).
- protection of the panel surfaces. Scratch-free panel processing is possible.

Working with the guide rail

The guide rail (4), together with the guide notch (3) in the machine table, guarantees straight machine guidance.



Machine with guide rail

Fig. 67309

1. Place the guide rail (4) on the work surface. The guide rail does not have to be fastened when used horizontally. The bottom side is slip-resistant.

Note


To extend the guide rail, join two single guide rails with connectors.

2. Place the machine support table (2) with the guide notch (3) on the guide rail (4).

4.6 Cutting along scribed line

When working without a guide rail, a scribed line might be of help when cutting straight cuts.

The distance between the blade and the edge of the table is 40 mm. This distance can be used to cut along a scribed line.




Straight cut with scribed line

Fig. 67310

Using the table markings at the front and back (see "Fig. 67308", pg. 19), the cut can be made at the marking directly. Make sure that the markings are always above the line or cut.

4.7 Slide rails and wearing plate

The wearing plate (1) on the bottom side of the machine table (2) guarantees a good cut quality and protects the machine while processing on the work table. To avoid scratches when processing panels, the bottom side of the machine table is equipped with 2 slide rails (3) made of plastic and a wearing plate at the front.



Bottom of tool table with wearing plate and slide rails

Fig. 67311

Replacing the slide rails

Each slide rail is held in place by 4 screws.

1. Remove the 4 screws of the slide rail.
2. Change worn slide rails.
3. Refasten the new slide rail with the 4 screws.

Replacing the wearing plate

The wearing plate is held in place by 8 screws.

1. Remove the 8 screws of the wearing plate.
2. Turn the wearing plate (worn on one side) by 180°. Change wearing plates worn on both sides.
3. Refasten the wearing plate with the screws.

Replacing the front wearing plate

The wearing plate is held in place by 3 screws.

1. Remove the 2 screws of the wearing plate.
2. Replace the worn wearing plate.
3. Refasten the wearing plate with the screws.

4.8 Exhaust system

WARNING

Escaping particles pose a health hazard!

- Use suction. Suctioning will protect the user from harmful particles and will keep the work environment free of unpleasant dust.

The machine is equipped with a suction connection piece (1) (35 mm, DIN 44717-A35).





Fig. 67312

The suction devices (2) to be connected, such as an industrial vacuum cleaner, must be suitable for coarse dust and hot metal filings.

4.9 Electronic signal display

On the motor, there is an electronic signal display next to the shown markings.



Electronic signal display

Fig. 67536

Status	Description
The electronic signal display is illuminated and the load speed decreases.	The winding temperature is too high! Let the machine run idle until the electronic signal display goes out.
The electronic signal display flashes and the machine does not run.	The restart protection responded. If the power plug is plugged in while the machine is switched on or if the power supply is reestablished after an interruption, the machine does not start up. Switch the machine off and on again.

Tab. 7

5. Maintenance and repairs

5.1 Maintenance



Maintenance points on the Panel Cutter TPC 165

Fig. 67313

Maintenance point	Procedure and interval	Recommended lubricants	Lubricant Order No.
Ventilation slots (4)	Clean as needed. ¹	-	-
Oil channel	Clean as needed.	-	-
Saw chain (3)	Refill with oil as needed (2). One oil filling is usually sufficient for a cutting length of approx. 150 m.	<ul style="list-style-type: none"> ▪ Punching and nibbling oil (1 x 500 ml) ▪ BLASER Vascomill USK 10 ▪ Other chain oils with viscosity VG 5-6, DIN 51550/51562 	103387
Gearbox and gear head (1)	After 100 operating hours, arrange for a trained specialist to regrease or to replace the lubricating grease.	Lubricating grease "G1"	139440
Set screw (see maintenance point "Set screw - Adjusting the ratchet")	If engagement or disengagement no longer works reliably.	-	-

Maintenance positions and maintenance intervals

Tab. 8

¹ It is recommended to blow out with compressed air when running idle.

Set screw - Adjusting the ratchet



Fig. 67465




Fig. 67462

- With the set screw (1), adjust the position of the catch (2) so that this is approx. 1 - 2 mm away from the ratchet disc (3) when actuated.

5.2 Repairs

 **WARNING**

Risk of injury due to incorrect repair work

Machine does not work properly.

- Maintenance may be carried out by trained specialist technicians only.
 - Repairs by TRUMPF Service.
 - Use recommended lubricant.
-

Replacing carbon brushes

The motor comes to a standstill whenever the carbon brushes are worn out.

Notes

- Use only original spare parts from TRUMPF.
 - Observe the information on the rating plate.
-
- Have the carbon brushes checked and replaced as required by a qualified technician.

6. Accessories and consumables

	Scope of delivery	Consumables	Accessories	Order number
Saw chain 165	X	X	-	1730983
Blade 165	X	X	-	1809537
Slide rails (2x)	X	X	-	1814882
Wearing plate	X	X	-	1814819
Wearing plate, front	X	X	-	1814820
Combination wrench	X	-	-	1797742
Case	X	-	-	1798090
Operator's manual TruTool TPC 165 (1A1)	X	-	-	1805994
Safety information	X	-	-	0125699
Punching and nibbling oil 1 x 500 ml)	X	-	-	0103387
Guide rail 1400 mm	-	-	X	1831777
Connector for guide rail	-	-	X	1831778

Accessories and consumables

Tab. 9

6.1 Ordering consumables

Note

The following data must be specified in order to ensure that parts are delivered correctly and without delay.

1. Specify the order number.
2. Enter further order data:
 - Voltage data
 - Quantity
 - Machine type
3. Specify the complete shipping information:
 - Correct address.
 - Desired delivery type (e.g. air mail, courier, express mail, ordinary freight, parcel post).

Note

For TRUMPF service addresses, see www.trumpf-powertools.com.

4. Send the order to the TRUMPF representative office.

**7. Appendix: Declaration of conformity,
guarantee, replacement parts lists**