



## TruTool TKF 1500 (3B1)

订购号 备件			
No. D'ORDINE	PEZZO DI RICAMBIO	31	1965561
NO. DE REF.	PIEZA DE RECAMBIO	32	0026239
NO. DE REF.	PIECE DE RECHANGE	33	2242737
ORDER NO.	SPARE PART	34	2242739
NO BEST.-NR.	ERSATZTEIL	35	2271393 D 230V 50/60Hz
			2271395 CH 230V 50/60Hz
			2271396 GB 110V 50Hz
			2271397 USA 120V 50/60Hz
1	2268901	36	2250447
2	0004810	37	2242479 D 230V 50/60Hz
3	0120740		2242479 CH 230V 50/60Hz
4	0119668		2242480 GB 110V 50Hz
5	2223215		2243574 USA 120V 50/60Hz
6	0026522	38	1927278
7	0021563	39	2282875
8	1978549	40	0030856
9	2083640	41	1971098
10	2282569	42	2082064
11	0112902	43	2279597
12	0112915	44	2077631
13	1973443	45	2228150
14	0112909	46	1263021 2x Standard
15	2083556		2278690 Al
16	0112892		1264417 2x Cr
17	0120719		1327480 2x Cr 5575
18	0112893	1264420 2x high performance Cr	
19	0115464	47	0118505
20	0010731	48	2269006
21	1965757	49	0021164
22	0148286	50	0027529
23	2082175	51	0023268
24	0113714	52	0014915
25	2083555	53	0207428
26	0751569	54	0016020
27	0129834	55	1884873
28	1973284	56	0125975
29	0023337	57	0020214
30	0119669		




---



---



---



---



---

	<b>TruTool TKF 1500 (3B1)</b>	

订货号 备件			
No. D'ORDINE	PEZZO DI RICAMBIO	78	0031566
NO. DE REF.	PIEZA DE RECAMBIO	79	0016870
NO. DE REF.	PIECE DE RECHANGE	80	0031125
ORDER NO.	SPARE PART	81	0032298
NO BEST.-NR.	ERSATZTEIL	82	0125974
		83	0023229
58	0017310	84	0023206
59	0031124	85	0017302
60	0032297	86	1238982
61	2038593	87	0149623
62	0013242	88	0020214
63	0010880	89	0117591
64	0031131	90	0117380
65	0031202	91	0022373
66	0063963		
67	0063962		
68	0011525		
69	0011428		
70	0063961		
71	0063964		
72	0020842		
73	0014524		
74	0023262		
75	0015555		
76	0016020		
77	0064130		

